






**PAGER** 

Version 3

## M 6.1, 22 km NE of Kupang, Indonesia

Origin Time: 2023-11-01 21:04:46 UTC (Thu 05:04:46 local) Location: 10.0123° S 123.7284° E Depth: 36.1 km

**Estimated Fatalities** 10,000 1,000



**Estimated Population Exposed to Earthquake Shaking** 

			•							
ESTIMATED POPULATION EXPOSURE (k=x1000)		_*	1,680k*	1,498k	649k	2k	0	0	0	0
ESTIMATED MODIFIED MERCALLI INTENSITY		I	11-111	IV	V	VI	VII	VIII	IX	X+
PERCEIVED SHAKING		Not felt	Weak	Light	Moderate	Strong	Very Strong	Severe	Violent	Extreme
POTENTIAL DAMAGE	Resistant Structures	None	None	None	V. Light	Light	Moderate	Mod./Heavy	Heavy	V. Heavy
	Vulnerable Structures	None	None	None	Light	Moderate	Mod./Heavy	Heavy	V. Heavy	V. Heavy

<sup>\*</sup>Estimated exposure only includes population within the map area.

## Population Exposure

population per 1 sq. km from Landscan

# Overall, the population in this region resides in structures that are vulnerable to earthquake shaking, though resistant structures exist. The predominant vulnerable building types are unreinforced brick with concrete floor and precast concrete frame with wall construction. Naisano Dua 9.8°S 10.9°S

**Structures** 

## **Historical Earthquakes**

Date	Dist.	Mag.	Max	Shaking
(UTC)	(km)		MMI(#)	Deaths
1995-05-21	210	5.2	VII(70k)	1
1977-08-27	272	7.0	VIII(1k)	2
1987-11-26	199	6.5	VIII(6k)	37

Recent earthquakes in this area have caused secondary hazards such as landslides that might have contributed to losses.

### Selected City Exposure

City	Population
Oeteta	<1k
Pariti	<1k
Bipolo	<1k
Taklale	<1k
Merdeka	<1k
Babau	<1k
Kupang	282k
Suai	22k
Maliana	22k
Liquica	19k
	Oeteta Pariti Bipolo Taklale Merdeka Babau Kupang Suai Maliana

bold cities appear on map.

(k = x1000)

PAGER content is automatically generated, and only considers losses due to structural damage. Limitations of input data, shaking estimates, and loss models may add uncertainty.